

1. Make an ice bath with ice and water (with ice above the water level)

2. Insert the probe into the ice bath – should be 32 degrees F

3. If not 32 degrees F, press the HOLD/CAL button for 4 seconds

4. Release the HOLD/CAL button when CAL starts flashing on the display

5. Once 32 degrees F displays, the calibration is complete



## Thermometer Calibration: It's a Weekly Thing